


Project **COMPRESSOR BALANCE LINE REPAIR**

Industry **Petrochemicals**
 City **Al Jubail**
 Country **Saudi Arabia**
 Equipment **Elliott Product Gas Compressor**
 Scope **The customer called AST Turbo to support on a serious balance line problem. The balance line showed cracks on the stub-outs on both ends. AST Turbo Engineering analyzed the situation and proposed a short term as well as a permanent solution within a very short time.**

FIELD SERVICES
PROJECT MANAGEMENT
QA/QC & AUDITS
UPGRADES
CONSULTING & ENGINEERING
REPAIR SOLUTIONS
PRODUCTS
TRAINING
TOOLS



Project Keywords
 Site **Petrochemicals, Al Jubail, Saudi Arabia**
 Scope **Design Engineering, RCFA, FEA, process parameters**
 Equipment **Elliott centrifugal compressor, API 617, 20 MW**